


Color Temperature Guide



CORRELATED COLOR TEMPERATURE (CCT): The measurement of the color appearance of light given off when heated to a certain temperature measured in Kelvin. Terms such as "warm" or "cool" are used to measure a light's appearance. Lights 3200 K and below are considered "warm" and 4000 K and up are considered "cool".